

**ARAB REPUBLIC OF EGYPT  
MINISTRY OF TRANSPORT  
EGYPTIAN AUTHORITY FOR MARITIME SAFETY**

**Notice to Mariners No. 14/2025**

**MEDIT SEA - PORT SAID :**

For shipmasters, shipping companies, and their agents, kindly be notified that, the following additions and deletions have been made to ensure the safety of maritime navigation in the area:

1- Deletion of the anchoring area at the following location:

| Serial No. | Name                     | Location                           |
|------------|--------------------------|------------------------------------|
| 1          | North Anchorage (Zone 1) | Lat 31° 27.5' N , Long. 032° 19' E |

2- Addition of anchoring areas at the following locations:

| Serial No. | Name                     | Location                           |
|------------|--------------------------|------------------------------------|
| 1          | North Anchorage (Zone 1) | Lat. 31° 28' N , Long 32° 18' E    |
| 2          | Echo Anchorage Area      | Lat . 31° 22.5' N, Long 032° 28' E |

Addition of cargo Transhipment at the following locations :

| Serial No. | Name    | Location                            |
|------------|---------|-------------------------------------|
| 1          | Area D1 | Lat . 31° 27' N , Long 32° 29.5' E  |
| 2          | Area D2 | Lat. 31° 25.5' N, Long 032° 29.5' E |

- All buoys should take into account safety sailing precautions, and all seafarers should apply.
- Affected Charts : M23-INT3500
- Alexandria- 15/11/2025