

**ARAB REPUBLIC OF EGYPT
MINISTRY OF TRANSPORT
EGYPTIAN AUTHORITY FOR MARITIME SAFETY**

Notice to Mariners No. 6/ 2025

Suez Canal :

For shipmasters, shipping companies, and their agents, kindly be notified that the following have been amended and deleted on the affected nautical charts to ensure maritime safety in the area :

1. Chart F (Kabrit to Suez) at the following location :

Buoy adjustment at the following location : Lat. 30° 15'.50 N & Long. 032° 30.90 E

South Cardinal Buoy	
Properties	
Colour	Yellow- Black
Lighting Frequency	Quick Flash every 6 seconds + Long Flash for 10 seconds

2. Chart E (Great Bitter Lakes) at the following location :

Buoy adjustment at the following location: Lat. 30° 15'.50 N & Long. 032° 30.90 E

South Cardinal Buoy	
Properties	
Colour	Yellow- Black
Lighting Frequency	Quick Flash every 6 seconds + Long Flash for 10 seconds

Buoy adjustment at the following location: Lat. 30° 17'.03 N & Long. 032° 26.21 E

North Cardinal Buoy	
Properties	
Colour	Yellow- Black
Lighting Frequency	Quick Flash every 3 seconds

Buoys Removal at the Location

Ser.	Buoy Type	Location
1	West Cardinal Buoy	Lat. 30° 16'.99 N & Long. 032° 26.32 E
2	Left Side No.17	Lat. 30° 18'.29 N & Long. 032° 23.87 E

- All buoys should take into account safety sailing precautions, and all seafarers should apply .
- Affected Chart No. SC02(INT 7159)
- Alexandria. 11/3/2025